NTSB Identification: Unknown

14 CFR Part 91 General Aviation

Aircraft: DEHAVILLAND 1046BA, registration: N4267C

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA F S M/N PURPOSE

2-0103 64/1/9 STUART FLA DEHAVILLAND 1046BA CR- 2 0 0 MISCELLANEOUS

ART FLA DEHAVILLAND 1046BA CR- 2 0 0 MISCELLANEOUS AIRLINE TRANSPORT, AGE
N4267C PX- 0 0 0 FERRY 25, 4035 TOTAL HOURS, 210
DAMAGE-DESTROYED OT- 0 0 0 IN TYPE, NOT INSTRUMENT TIME - 1100

RATED.

NAME OF AIRPORT - WITHAM FIELD

TYPE OF ACCIDENT PHASE OF OPERATION PHASE OF OF EACH TAKEOFF: INITIAL CLIMB STALL PROBABLE CAUSE(S)

PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT

REMARKS- SIMULATED SINGLE-ENGINE TAKEOFF

Full narrative is not available