

NTSB Identification: FTW66A0100

14 CFR Part 91 General Aviation
Aircraft: BEECH D18S, registration: N189L

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
2-0415	66/5/11	HOUSTON TEX	BEECH D18S	CR-	2	0 0	NONCOMMERCIAL	COMMERCIAL, FL.INSTR., AGE 49, 9500 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
	TIME - 1155		N189L	PX-	3	0 0	CORP/EXEC	
			DAMAGE-DESTROYED	OT-	0	0 0		
NAME OF AIRPORT - WILLIAM P HOBBY								
TYPE OF ACCIDENT				PHASE OF OPERATION				
GEAR RETRACTED				TAKEOFF: RUN				
STALL: SPIN				TAKEOFF: INITIAL CLIMB				
PROBABLE CAUSE(S)								
PILOT IN COMMAND - RETRACTED GEAR PREMATURELY								
PILOT IN COMMAND - FAILED TO ABORT TAKEOFF								
FIRE AFTER IMPACT								
REMARKS- N189L NEEDED MORE THAN 1525 FT GROUND ROLL FOR TAKEOFF.PROPS HIT RNWY 1058 FT.FROM START OF ROLL.								

Full narrative is not available