NTSB Identification: LAX69A0027

14 CFR Part 91 General Aviation Aircraft: CONVAIR 580, registration: N73135

FILE	DATE	LOCATION	AIRCRAFT DATA			IES S M		FLIGHT PURPOSE	PILOT DATA
3-4638	68/11/12 TIME - 172	,	CONVAIR 580 N73135 DAMAGE-SUBSTANTIAL	PX-	0	0	1	INSTRUCTIONAL DUAL	COMMERCIAL, FL.INSTR., AGE 51, 4741 TOTAL HOURS, 866 IN TYPE, INSTRUMENT

NAME OF AIRPORT - SANTA BARBARA
TYPE OF ACCIDENT
WHEELS-UP
PROBABLE CAUSE(S)
DUAL STUDENT - FAILED TO EXTEND LANDING GEAR
PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT

FACTOR(S)
MISCELLANEOUS ACTS, CONDITIONS - CHECKLIST-FAILED TO USE
AIRFRAME - LANDING GEAR: LANDING GEAR WARNING AND INDICATING COMPONENTS
REMARKS- LNDG GR WARNING HORN INOPERATIVE FOR UNDETERMINED REASON.

Full narrative is not available

PHASE OF OPERATION
LANDING: LEVEL OFF/TOUCHDOWN