

# NTSB Identification: FTW69A0038

14 CFR Part 91 General Aviation  
 Aircraft: CESSNA 411, registration: N7392U

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4700	68/12/7 TIME - 1117	HOUSTON, TEX	CESSNA 411 N7392U DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL BUSINESS	COMMERCIAL, AGE 49, 3500 TOTAL HOURS, 300 IN TYPE, INSTRUMENT RATED.
		NAME OF AIRPORT - HOBBY INTL			PHASE OF OPERATION	
		TYPE OF ACCIDENT			TAKEOFF: INITIAL CLIMB	
		ENGINE FAILURE OR MALFUNCTION			TAKEOFF: INITIAL CLIMB	
		STALL: SPIN				
		PROBABLE CAUSE(S)				
		POWERPLANT - FUEL SYSTEM: PUMPS				
		MISCELLANEOUS ACTS,CONDITIONS - LOOSE,PART/FITTING				
		MISCELLANEOUS ACTS,CONDITIONS - LEAK/LEAKAGE				
		MISCELLANEOUS ACTS,CONDITIONS - LACK OF LUBRICATION-SPECIFIC PART,NOT SYSTEM				
		MISCELLANEOUS ACTS,CONDITIONS - SCORED				
		MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION				
		PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION				
		MISCELLANEOUS ACTS,CONDITIONS - IMPROPER EMERGENCY PROCEDURES				
		PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED				
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE				
		REMARKS- LOOSE,LEAKING FITTING IN ENG DRIVEN FUEL PUMP.BEARING DRY,ARMATURE SCORED IN AUX FUEL PUMP.L ENG.				

Full narrative is not available