NTSB Identification: MIA72OKT38

14 CFR Part 91 General Aviation Aircraft: BEECH B90, registration: N480K

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA	
3-3732	TIME - 15		N480K DAMAGE-DESTROYED NTENDED DESTINATION	PX-	0	0	0		COMMERCIAL, AGE 44, 12300 TOTAL HOURS, 200 IN TYPE, INSTRUMENT RATED.	
	TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION DITCHING PROBABLE CAUSE(S) PILOT IN COMMAND - MISMANAGEMENT OF FUEL MISCELLANEOUS ACTS, CONDITIONS - MISCALCULATED									
	MISCELLANEOUS ACTS, CONDITIONS - FUEL EXHAUSTION FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - FAILURE OF TWO OR MORE ENGINES POWERPLANT - POWERPLANT-INSTRUMENTS: OTHER MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER REMARKS- PLT STATED FUEL TOTALIZER SHOWED 387LBS, FUEL GAUGES SHOWED ZERO.DITCHED 18NM S OF FREEPORT, SANK.								DF FREEPORT,SANK.	

Full narrative is not available