

NTSB Identification: MIA80FA090

14 CFR Part 91 General Aviation
Aircraft: PIPER PA-31, registration: N27906

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|---|------------------------|----------------------|---|-------------------------------------|-----------------------|--|
| 3-2666 | 80/8/10 TIME - 2020 | DANIA, FL | PIPER PA-31 N27906 DAMAGE-DESTROYED | CR- 2 0 0 PX- 0 0 0 OT- 0 0 0 | MISCELLANEOUS TEST | PRIVATE, AGE 31, 186 TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. |
| NAME OF AIRPORT - HOLLYWOOD INTL | | INTENDED DESTINATION | | | | |
| DEPARTURE POINT DANIA, FL | | LOCAL | | | | |
| TYPE OF ACCIDENT GEAR RETRACTED | | | | PHASE OF OPERATION TAKEOFF: RUN | | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - RETRACTED GEAR PREMATURELY | | | | | | |
| FIRE AFTER IMPACT | | | | | | |
| REMARKS- ACFT SETTLED AFTR GR RETRACTION.ALL PROPS DMGD DUE CONTACT WITH RWY. | | | | | | |

Full narrative is not available