

NTSB Identification: LAX80FUG58

14 CFR Part 91 General Aviation
Aircraft: CESSNA 421, registration: N4091L

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-3003	80/9/19	PALM SPRINGS,CA	CESSNA 421	CR-	0	0	1	NONCOMMERCIAL	COMMERCIAL, AGE 62, 3963 TOTAL HOURS, 362 IN TYPE, INSTRUMENT RATED.
	TIME - 1342		N4091L	PX-	0	0	1	BUSINESS	
			DAMAGE-DESTROYED	OT-	0	0	0		
		NAME OF AIRPORT - PALM SPRINGS							
		DEPARTURE POINT	INTENDED DESTINATION						
		PALM SPRINGS,CA	BURBANK,CA						
		TYPE OF ACCIDENT						PHASE OF OPERATION	
		ENGINE FAILURE OR MALFUNCTION						TAKEOFF: INITIAL CLIMB	
		COLLIDED WITH: TREES						LANDING: FINAL APPROACH	
		PROBABLE CAUSE(S)							
		POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS							
		FACTOR(S)							
		TERRAIN - HIGH OBSTRUCTIONS							
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE							
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND							
		REMARKS- PILOT STATED RIGHT ENGINE FAILED AND PROP WOULD NOT FEATHER.NO FAILURES REVEALED BY ENGINE INSP.							

Full narrative is not available