

# NTSB Identification: ANC80FA103

14 CFR Part 135 Nonscheduled operation of WINDWARD PASSA  
 Aircraft: ROBERTSON 207A, registration: N6244H

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3644	80/9/28 TIME - 1105	NR.NIKISKI,AK	ROBERTSON 207A N6244H DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 1 0 OT- 0 0 0	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, AGE 26, 2301 TOTAL HOURS, 1203 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - BUTLER AVIATION DEPARTURE POINT NIKISKI,AK INTENDED DESTINATION RETURN LAST ENROUTE STOP KALGIN ISLAND,AK TYPE OF ACCIDENT COLLIDED WITH: TREES PHASE OF OPERATION TAKEOFF: INITIAL CLIMB PROBABLE CAUSE(S) PILOT IN COMMAND - MISUSED OR FAILED TO USE FLAPS PILOT IN COMMAND - PREMATURE LIFT-OFF FACTOR(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G. WEATHER - DOWNDRAFT,UPDRAFTS WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED WEATHER FORECAST - UNKNOWN/NOT REPORTED SKY CONDITION BROKEN CEILING AT ACCIDENT SITE 2500 VISIBILITY AT ACCIDENT SITE 5 OR OVER(UNLIMITED) PRECIPITATION AT ACCIDENT SITE UNKNOWN/NOT REPORTED OBSTRUCTIONS TO VISION AT ACCIDENT SITE NONE TYPE OF WEATHER CONDITIONS VFR TYPE OF FLIGHT PLAN NONE REMARKS- FULL FLAP TKOF.OVER MAX GWT.						

Full narrative is not available