NTSB Identification: SEA80FA042

14 CFR Part 135 Nonscheduled operation of SALMON AIR TAX Aircraft: CESSNA T207, registration: N91115

FILE	DATE LOCA	ATION AIRCRAFT DA	TA II				FLIGHT PURPOSE	PILOT DATA
3-1729	80/8/11 NR.SALMON, TIME - 1945			1	0	0	COMMERCIAL AIR TAXI-CARGO	COMMERCIAL, FL.INSTR., AGE 20, 1187 TOTAL HOURS 70 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT	INTENDED DESTINA						
	SALMON, ID	INDIAN CREEK,I	D					
	TYPE OF ACCIDENT			F			F OPERATION	
	STALL				Ι	N F	LIGHT: OTHER	
	PROBABLE CAUSE(S)							
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED							
	FACTOR(S) MISCELLANEOUS ACTS,CONDITIONS - UNWARRANTED LOW FLYING WEATHER - HIGH DENSITY ALTITUDE							
	WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED							
	WEATHER FORECAST -	UNKNOWN/NOT REPORTED						
	SKY CONDITION			(EIL			
	CLEAR						ITED	
	VISIBILITY AT ACCIDENT SITE			F			TATION AT ACCIDENT SI	TE
	5 OR OVER(UNLIMITED)				NO			
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE			1			TURE-F	
	NONE			-	8		FLICHT DIAN	
	TYPE OF WEATHER CONDITIONS VFR FIRE AFTER IMPACT				NO		FLIGHT PLAN	
	LIKE ALIEK IMPACI							

Full narrative is not available