

NTSB Identification: LAX70AL054

14 CFR Part 91 General Aviation
 Aircraft: STINSON V-77, registration: N69440

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0758	70/3/7 TIME - 1404	PERRIS,CALIF	STINSON V-77 N69440 DAMAGE-DESTROYED	CR- 0 1 0 PX- 1 0 4 OT- 0 0 0	MISCELLANEOUS PARAJUMP-SPORT	COMMERCIAL, AGE 27, 800 TOTAL HOURS, 252 IN TYPE, NOT INSTRUMENT RATED.
NAME OF AIRPORT - PERRIS						
DEPARTURE POINT		INTENDED DESTINATION				
PERRIS,CALIF		LOCAL				
TYPE OF ACCIDENT						
AIRFRAME FAILURE: IN FLIGHT				PHASE OF OPERATION		
				IN FLIGHT: OTHER		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PILOT IN COMMAND - EXERCISED POOR JUDGMENT						
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.						
PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION						
AIRFRAME - WINGS: SKIN AND ATTACHMENTS						
MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.						
FACTOR(S)						
MISCELLANEOUS ACTS,CONDITIONS - OVERLOAD FAILURE						
REMARKS- METAL SKIN CVRG TOP L WING LOOSE,SKIN WORKING,SEPN OCRD.PLT EXCEEDED ACFT OPNS LIMITS BFR OCRNC.						

Full narrative is not available