NTSB Identification: Unknown

14 CFR Part 91 General Aviation Aircraft: BEECH 65, registration: N451HC

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA

F S M/N PURPOSE

COMMERCIAL, FL.INSTR.,

INSTRUMENT RATED.

NAME OF AIRPORT - LOGAN FIELD

TYPE OF ACCIDENT PHASE OF OPERATION

ENGINE FAILURE OR MALFUNCTION LANDING: FINAL APPROACH

LANDING: FINAL APPROACH STALL

PROBABLE CAUSE(S)

PILOT IN COMMAND - MISMANAGEMENT OF FUEL

MISCELLANEOUS ACTS, CONDITIONS - INATTENTIVE TO FUEL SUPPLY

COPILOT - MISMANAGEMENT OF FUEL

MISCELLANEOUS ACTS, CONDITIONS - INATTENTIVE TO FUEL SUPPLY

PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT

MISCELLANEOUS ACTS, CONDITIONS - FUEL STARVATION

FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES

MISCELLANEOUS ACTS, CONDITIONS - FAILURE OF TWO OR MORE ENGINES

PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE

COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE

FIRE AFTER IMPACT

Full narrative is not available