

NTSB Identification: MIA65D0068

14 CFR Part 135 Nonscheduled operation of JIM HILL ACFT
 Aircraft: BEEHCRAFT D-18S, registration: N9523Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-0764	65/4/9 TIME - 1405	NR.MIAMI FLA	BEEHCRAFT D-18S N9523Z DAMAGE-DESTROYED	CR- PX- OT-	0 0 0	1 0 0	COMMERCIAL AIR TAXI-CARGO	COMMERCIAL, FL.INSTR., AGE 36, 5587 TOTAL HOURS, 460 IN TYPE, INSTRUMENT RATED.
TYPE OF ACCIDENT				PHASE OF OPERATION				
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE				
DITCHING				LANDING: LEVEL OFF/TOUCHDOWN				
PROBABLE CAUSE(S)								
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS								
FACTOR(S)								
MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER								
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES								
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER								
REMARKS- WRECKAGE NOT RECOVERED FROM OCEAN.								

Full narrative is not available