

NTSB Identification: MIA66A0150

14 CFR Part 135 Nonscheduled operation of MCCOY FLYING SCHOOL
Aircraft: DOUGLAS DC-3, registration: N17337

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
2-1120	66/6/27	LONG BEACH,MISS	DOUGLAS DC-3	CR-	1	1	0	COMMERCIAL	COMMERCIAL, AGE 41, 2132
	TIME - 1115		N17337	PX-	1	9	0	AIR TAXI-PASSG	TOTAL HOURS, UNK/NR IN
			DAMAGE-DESTROYED	OT-	0	0	0		TYPE, INSTRUMENT RATED.
TYPE OF ACCIDENT				PHASE OF OPERATION					
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: CLIMB TO CRUISE					
STALL				LANDING: FINAL APPROACH					
PROBABLE CAUSE(S)									
POWERPLANT - ENGINE STRUCTURE: PISTON,PISTON RINGS									
MISCELLANEOUS ACTS,CONDITIONS - OIL STARVATION									
PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION									
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED									
PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING									
PILOT IN COMMAND - IMPROPER OPERATION OF POWERPLANT & POWERPLANT CONTROLS									
MISCELLANEOUS ACTS,CONDITIONS - CREW COORDINATION-POOR									
MISCELLANEOUS ACTS,CONDITIONS - IMPROPER EMERGENCY PROCEDURES									
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE									
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND									
FIRE AFTER IMPACT									
REMARKS- GR.DID NOT RETRACT. NO.3 PISTON R.ENG FAILED.SUITABLE EMER.ARPT OVERFLWN.R.ENG PROP NOT FEATHERED.									

Full narrative is not available