

NTSB Identification: DEN67A0035

14 CFR Part 91 General Aviation
 Aircraft: BEECH 65-88, registration: N886E

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
2-1081	66/12/6 TIME - 1517	WOODS CROSS UTAH	BEECH 65-88 N886E DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 0 0 OT- 0 0 0	INSTRUCTIONAL DUAL	ATP, FLIGHT INSTR., AGE 40, 13000 TOTAL HOURS, 100 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - SKY HAVEN						
TYPE OF ACCIDENT						
FIRE OR EXPLOSION: IN FLIGHT			PHASE OF OPERATION			
COLLISION WITH GROUND/WATER: CONTROLLED			IN FLIGHT: CLIMB TO CRUISE			
PROBABLE CAUSE(S)			IN FLIGHT: EMERGENCY DESCENT			
MISCELLANEOUS ACTS, CONDITIONS - *ERROR-INVALID CODE*						
MISCELLANEOUS - SMOKE IN COCKPIT						
MISCELLANEOUS ACTS, CONDITIONS - FIRE IN CABIN, COCKPIT, BAGGAGE COMPARTMENT						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
SMOKE IN COCKPIT						
REMARKS- THREE MINUTES AFTER PASSING 9000 FT ON CLIMB TO 13000 FT PILOT DECLARED EMERGENCY-SMOKE IN COCKPIT						

Full narrative is not available