

# NTSB Identification: MIA67A0107

14 CFR Part 135 Nonscheduled operation of LUIS PAGAN-PAG  
Aircraft: BEECH C-45G, registration: N9470Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4659	67/3/19 TIME - 1315	ARECIBO, PR	BEECH C-45G N9470Z DAMAGE-DESTROYED	CR- 0 0 3 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-CARGO	COMMERCIAL, AGE 47, 12200 TOTAL HOURS, 165 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - ARECIBO						
TYPE OF ACCIDENT		PHASE OF OPERATION				
ENGINE FAILURE OR MALFUNCTION		TAKEOFF: INITIAL CLIMB				
COLLIDED WITH: DITCHES		LANDING: LEVEL OFF/TOUCHDOWN				
PROBABLE CAUSE(S)						
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS						
PILOT IN COMMAND - FAILED TO MAINTAIN DIRECTIONAL CONTROL						
FACTOR(S)						
MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIP.T.						
REMARKS- STRUCK A DITCH.IMPROPER SINGLE ENG.PROCEDURE.						

Full narrative is not available