NTSB Identification: SEA69F0173

14 CFR General Aviation Forn Aircraft: BEECH D18S, registration: CF-RQL

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA
F S M/N PURPOSE

E-0018 68/12/5 SEATTLE,WASH BEECH D18S CR- 0 0 1 NONCOMMERCIAL COMMERCIAL, AGE 31, 4207
TIME - 1410 CF-RQL PX- 0 0 0 CORP/EXEC TOTAL HOURS, 30 IN TYPE,
DAMAGE-DESTROYED OT- 0 0 0 NOT INSTRUMENT RATED.

NAME OF AIRPORT - BOEING
TYPE OF ACCIDENT
ENGINE FAILURE OR MALFUNCTION

ENGINE FAILURE OR MALFUNCTIC COLLIDED WITH: WIRES/POLES PROBABLE CAUSE(S)

PILOT IN COMMAND - MISMANAGEMENT OF FUEL
MISCELLANEOUS ACTS, CONDITIONS - FUEL STARVATION
FACTOR(S)
MISCELLANEOUS ACTS CONDITIONS - CHECKLIST-FAILER

MISCELLANEOUS ACTS, CONDITIONS - CHECKLIST-FAILED TO USE
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND
FIRE AFTER IMPACT
REMARKS- FUEL SELECTOR ON NOSE TANK.ACFT ALSO HIT 7 CARS.

Full narrative is not available

PHASE OF OPERATION
LANDING: FINAL APPROACH
LANDING: FINAL APPROACH