## NTSB Identification: CHI69A0031

14 CFR Part 135 Scheduled operation of SUN AIRLINES \* Aircraft: CESSNA 402, registration: N3259Q

FILE	DATE	LOCATION	AIRCRAFT DATA			IES S M		FLIGHT PURPOSE	PILOT DATA
3-4452	68/9/17 TIME - 195	PADUCAH,KY 55	CESSNA 402 N3259Q DAMAGE-DESTROYED	PX-	0	0	1	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	COMMERCIAL, FL.INSTR., AGE 21, 1684 TOTAL HOURS, 210 IN TYPE, INSTRUMENT

NAME OF AIRPORT - BARKLEY
TYPE OF ACCIDENT
COLLISION WITH GROUND/WATER: CONTROLLED

PHASE OF OPERATION
TAKEOFF: INITIAL CLIMB
TAKEOFF: INITIAL CLIMB STALL

PROBABLE CAUSE(S)

PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
FIRE AFTER IMPACT

REMARKS- MAIL FLT.IMPROPER ANGLE OF CLIMB, ALLOWED PROPS TO CONTACT RNWY. ABRUPT ASCENT WITH DAMAGED PROPS.

Full narrative is not available