NTSB Identification: ANC69A0049

14 CFR Part 91 General Aviation Aircraft: CANADAIR CL44, registration: N446T

FILE	DATE LOCATION	AIRCRAFT DATA	INJURIES FLIGHT F S M/N PURPOSE	PILOT DATA
3-3871	69/5/1 ANCHORAGE,ALAS	CANADAIR CL44 N446T DAMAGE-DESTROYED	CR- 0 1 2 NONCOMMERCIAL PX- 0 1 0 CORP/EXEC OT- 0 0 0	AIRLINE TRANSPORT, AGE 28, 4000 TOTAL HOURS, 350 IN TYPE, INSTRUMENT RATED.
	NAME OF AIRPORT - ANCHORA DEPARTURE POINT	AGE INTL INTENDED DESTINATION	LAST ENROUTE STOP	

ANCHORAGE, ALAS
TYPE OF ACCIDENT
HARD LANDING WEST KAPARUK,ALAS PHASE OF OPERATION ANCHORAGE, ALAS LANDING: LEVEL OFF/TOUCHDOWN LANDING: ROLL

GEAR COLLAPSED

PROBABLE CAUSE(S)

COPILOT - IMPROPER LEVEL OFF
PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - PILOT FATIGUE
MISCELLANEOUS ACTS, CONDITIONS - SEAT BELT NOT FASTENED
MISCELLANEOUS ACTS, CONDITIONS - OVERLOAD FAILURE
FIRE AFTER IMPACT

REMARKS- AGFT LEASED TO MOBIL OIL COMPANY AND USED TO TRANSPORT FUEL OIL.CREW REST 3 TO 4HRS.PAX ASLEEP.

Full narrative is not available