## NTSB Identification: CHI71FDJ23

14 CFR Part 91 General Aviation Aircraft: CONVAIR PBY-5A, registration: N610FF

FILE	DATE	LOCATION	AIRCRAFT DATA	 	IES S M		FLIGHT PURPOSE	PILOT DATA
3-1467	70/10/15 TIME - 094	RHINELANDER,WIS 0	N610FF	 0	2	0	MISCELLANEOUS TEST	COMMERCIAL, FL.INSTR., AGE 56, 18717 TOTAL HOURS, 3507 IN TYPE, INSTRUMENT RATED.

INTENDED DESTINATION

NAME OF AIRPORT - ONEIDA COUNTY DEPARTURE POINT INTE RHINELANDER,WIS LO LOCAL

TYPE OF ACCIDENT PHASE OF OPERATION TAKEOFF: INITIAL CLIMB

STALL

PROBABLE CAUSE(S)

PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING

PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED

MISCELLANEOUS ACTS, CONDITIONS - AIRFRAME ICE

REMARKS- MINERAL RESEARCH, ELECT EQPT TEST FLT.T/O WITH APRX 50PCT FROST ACCUMULATION ON ACFT.

Full narrative is not available