## NTSB Identification: FTW72AF044

14 CFR Part 91 General Aviation Aircraft: GATES LEAR 25, registration: N658TC

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT F S M/N PURPOSE  3-0003 72/1/18 VICTORIA,TEX GATES LEAR 25 CR- 2 0 0 NONCOMMERCIAL COMMERCIAL, A	
	AGE 52, 15500
	AGE 22, 12200
TIME - 0745 N658TC PX- 7 0 0 CORP/EXEC TOTAL HOURS.	
DAMAGE-DESTROYED OT- 0 0 0 TYPE, INSTRUI	MENI KATED.
NAME OF AIRPORT - VICTORIA COUNTY	
TYPE OF ACCIDENT PHASE OF OPERATION	
COLLISION WITH GROUND/WATER: CONTROLLED LANDING: FINAL APPROACH	
PROBABLE CAUSE(S)	
PILOT IN COMMAND - IMPROPER IFR OPERATION	
PILOT IN COMMAND - MISJUDGED ALTITUDE	
FACTOR(S)	
WEATHER - LOW CEILING	
WEATHER - FOG	
WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY RADIO	
WEATHER FORECAST - WEATHER SLIGHTLY WORSE THAN FORECAST	
SKY CONDITION CEILING AT ACCIDENT SITE	
PARTIAL OBSCURATION 2800	
VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE	
1/4 MILE OR LESS NONE	
OBSTRUCTIONS TO VISION AT ACCIDENT SITE TEMPERATURE-F	
FOG 58	
TYPE OF WEATHER CONDITIONS TYPE OF FLIGHT PLAN	
BELOW MINIMUMS IFR	
FIRE AFTER IMPACT	
REMARKS- LACK OF ALT AWARENESS OF CREW ON DESCENT INTO KNOWN POOR VIS.ILLUSORY EFFECT PRESENT DUE FOG,SU	UN.

Full narrative is not available