

# NTSB Identification: NYC72FID17

14 CFR Part 91 General Aviation  
 Aircraft: BEECH H18, registration: N717Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3692	71/11/29 TIME - 1400	CHARLOTTESVILLE,VA	BEECH H18 N717Z DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL BUSINESS	COMMERCIAL, AGE 49, 15575 TOTAL HOURS, 485 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - CHARLOTTESVILLE						
DEPARTURE POINT		INTENDED DESTINATION				
LEXINGTON,KY		CHARLOTTESVILLE,VA				
TYPE OF ACCIDENT				PHASE OF OPERATION		
STALL				LANDING: MISSED APPROACH		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
FACTOR(S)						
PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS						
MISCELLANEOUS ACTS,CONDITIONS - INCORRECT TRIM SETTING						
WEATHER - LOW CEILING						
WEATHER - RAIN						
WEATHER - FOG						
WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE						
WEATHER FORECAST - WEATHER SLIGHTLY WORSE THAN FORECAST						
SKY CONDITION				CEILING AT ACCIDENT SITE		
OVERCAST				700		
VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE		
3/4 MILE OR LESS				RAIN		
OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F		
FOG				40		
WIND DIRECTION-DEGREES				WIND VELOCITY-KNOTS		
280				4		
TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN		
IFR				IFR		
REMARKS- LOST CTL ON GO AROUND FROM LOCALIZER APCH. FULL L RUDDER TRIM AND FULL FWD ELEVATOR TRIM FOUND.						

Full narrative is not available