NTSB Identification: MIA73FKJ53

14 CFR Part 91 General Aviation Aircraft: LOCKHEED PV-1, registration: N45CK

FILE	DATE	LOCATION	AIRCRAFT DATA			S M	/N	PURPOSE		PILOT DATA	
3-1061	TIME - 08	AIRPORT - FRANKLIN	LOCKHEED PV-1 N45CK DAMAGE-DESTROYED	PX-	0	0 0	0 0	COMMERCIAL	PLICATION	COMMERCIAL, AGE 51, 5100 TOTAL HOURS, 67 IN TYPE, NOT INSTRUMENT RATED.	
	MONTGOMERY,ALA MONTGOMERY,ALA										
						PHASE OF OPERATION					
	COLLISION WITH GROUND/WATER: CONTROLLED					IN FLIGHT: STARTING SWATH RUN					
	PROBABLE CAUSE(S)										
	PILOT IN COMMAND - MISJUDGED SPEED AND ALTITUDE										
	PILOT IN COMMAND - DIVERTED ATTENTION FROM OPERATION OF AIRCRAFT										
	FACTOR(S)										
	MISCELLANEOUS ACTS, CONDITIONS - JETTISONED LOAD										
	SPECIAL DATA						KIND OF OPERATION - SPRAYING FORESTS				
	TOTAL HOURS IN CROP CONTROL - UNKNOWN/NOT REPORTED KIND OF CROP - FOREST-TREES					TYPE OF CHEMICAL USED - DRY CHEMICAL-NONTOXIC					
	PILOT' S SEAT BELT -UNKNOWN/NOT REPORTED					GLOVES - NOT USED					
	GOGGLES - NOT USED					CRASH HELMET - AVAILABLE-NOT USED					
	COCKPIT CRASHPAD - NOT INSTALLED					CRASH BAR - NOT INSTALLED					
	TANK/HOPPER-LOCATION - AFT OF PILOT					ELEVATION-AREA BEING TREATED-FEET - 1000					
	SWATH RUN-HOW FLOWN - CROSSWIND					PROCEDURE TURNAROUND - THIRD 1/3 TURN					
	FIRE AFTER IMPACT										
	REMARKS- DRG DECCA CAL PRIOR FIRST SWATH RUN ACFT DSCNDD						AND HIT GND IN NEAR LVL FLT ATTITUDE.				

Full narrative is not available