

NTSB Identification: NYC74AN057

14 CFR Part 91 General Aviation
 Aircraft: CESSNA 411, registration: N424RF

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3525	73/12/21 TIME - 0750	ENDICOTT,NY	CESSNA 411 N424RF DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 0 4 OT- 0 0 0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, FL.INSTR., AGE 33, 4828 TOTAL HOURS, 268 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - TRI-CITIES DEPARTURE POINT INTENDED DESTINATION ENDICOTT,NY ONTARIO,CAN TYPE OF ACCIDENT PHASE OF OPERATION GROUND-WATER LOOP-SWERVE TAKEOFF: RUN GEAR COLLAPSED TAKEOFF: ABORTED PROBABLE CAUSE(S) PILOT IN COMMAND - SELECTED UNSUITABLE TERRAIN AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: SNOW ON RUNWAY PILOT IN COMMAND - DELAYED ACTION IN ABORTING TAKEOFF FACTOR(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING WEATHER - SNOW WEATHER - UNFAVORABLE WIND CONDITIONS MISCELLANEOUS ACTS,CONDITIONS - OVERLOAD FAILURE WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT SKY CONDITION CEILING AT ACCIDENT SITE OBSCURATION 100 VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE 1/2 MILE OR LESS SNOW OBSTRUCTIONS TO VISION AT ACCIDENT SITE TEMPERATURE-F NONE 27 WIND DIRECTION-DEGREES WIND VELOCITY-KNOTS 310 16 TYPE OF WEATHER CONDITIONS TYPE OF FLIGHT PLAN IFR IFR REMARKS- REDUCED PWR R ENG TO CORRECT SKID.UN TO OBTAIN TKOF SPD.OVERRAN RWY.						

Full narrative is not available