## NTSB Identification: CHI75AC026

14 CFR Part 135 Nonscheduled operation of MADISON NATION Aircraft: BEECH E18S, registration: N1258

| FILE   | DATE                  | LOCATION          | AIRCRAFT DATA                           |     |   | IES<br>S M |   | FLIGHT<br>PURPOSE            | PILOT DATA  |
|--------|-----------------------|-------------------|---|-----|---|------------|---|------------------------------|---|
| 3-3868 | 74/9/11<br>TIME - 001 | MADISON,IND<br>L0 | BEECH E18S<br>N1258<br>DAMAGE-DESTROYED | PX- | 0 | 0          | 0 | COMMERCIAL<br>AIR TAXI-CARGO | ATP,FLIGHT INSTR., AGE<br>27, 3366 TOTAL HOURS,<br>2000 IN TYPE, INSTRUMENT<br>RATED. |

NAME OF AIRPORT - MADISON MUNI
DEPARTURE POINT INTENDED DESTINATION
MADISON THE STRUCTON MY MADISON, IND LEXINGTON, KY

TYPE OF ACCIDENT
COLLIDED WITH: TREES

PHASE OF OPERATION
TAKEOFF: INITIAL CLIMB

PROBABLE CAUSE(S)

PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE

FACTOR(S)

TERRAIN - HIGH OBSTRUCTIONS

FIRE AFTER IMPACT

REMARKS- HIT TREES 50FT AGL ON RWY HDG,2300FT FM RWY END.LDG GR IN TRANSIT.

Full narrative is not available