

NTSB Identification: ANC75AA040

14 CFR Part 135 Scheduled operation of SOUTHEAST SKY*
 Aircraft: DEHAVILLAND DHC-2, registration: N9770Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4097	74/11/15	NR.HOONAH,ALAS	DEHAVILLAND DHC-2	CR- 1 0 0	COMMERCIAL	COMMERCIAL, AGE 32, 2864
	TIME - 1300		N9770Z	PX- 3 0 0	COMMUTER AIR CARRIER	TOTAL HOURS, 300 IN TYPE,
			DAMAGE-DESTROYED	OT- 0 0 0	AIR TAXI-PASSG S-D	INSTRUMENT RATED.
	DEPARTURE POINT		INTENDED DESTINATION			
	JUNEAU,ALAS		TENAKEE,ALAS			
	TYPE OF ACCIDENT				PHASE OF OPERATION	
	COLLISION WITH GROUND/WATER: CONTROLLED				IN FLIGHT: NORMAL CRUISE	
	PROBABLE CAUSE(S)					
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING					
	PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS					
	FACTOR(S)					
	WEATHER - LOW CEILING					
	WEATHER - SNOW					
	MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER					
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, IN PERSON					
	WEATHER FORECAST - UNKNOWN/NOT REPORTED					
	SKY CONDITION				CEILING AT ACCIDENT SITE	
	OVERCAST				UNKNOWN/NOT REPORTED	
	VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE	
	1/4 MILE OR LESS				SNOW	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F	
	BLOWING SNOW				32	
	WIND DIRECTION-DEGREES				WIND VELOCITY-KNOTS	
	60				45	
	TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN	
	IFR				VFR	
	REMARKS- FLOAT EQUIPPED. FLEW INTO BAY.					

Full narrative is not available