

NTSB Identification: NYC77FA050

14 CFR Part 91 General Aviation
 Aircraft: CONVAIR 240, registration: N10AV

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2654	77/4/9 TIME - 1315	HYANNIS,MA	CONVAIR 240 N10AV DAMAGE-DESTROYED	CR- 0 2 0 PX- 0 2 1 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	AIRLINE TRANSPORT, AGE 45, 15774 TOTAL HOURS, 600 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - BARNSTABLE						
DEPARTURE POINT		INTENDED DESTINATION				
HYANNIS,MA		LOCAL				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				LANDING: TRAFFIC PATTERN-CIRCLING		
COLLIDED WITH: OBJECT				LANDING: LEVEL OFF/TOUCHDOWN		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
MISCELLANEOUS ACTS,CONDITIONS - ICE-IN FUEL						
MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES						
TERRAIN - OTHER						
PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
REMARKS- ICE IN R FUEL TANK.CROSSFEED ON,BOOST PUMPS ON TANK VALVES BOTH ON.TRANSFER OCRD.ROCKS ON BEACH.						

Full narrative is not available