NTSB Identification: ANC77FA072

14 CFR General Aviation Forn Aircraft: BEECH H18, registration: C-GWUY

| FILE | DATE | LOCATION | AIRCRAFT DATA | | INJURIES | | | FLIGHT | PILOT DATA | |
|--------|---|----------------------|----------------------|-----|--------------------|--------------------------------|-----------------------|--------------------------|-------------------------|--|
| | | | | | F | S M | /N | PURPOSE | | |
| E-0010 | 77/8/11 | NR.WRANGELL,AK | BEECH H18 | CR- | 1 | 0 | 0 | NONCOMMERCIAL | PRIVATE, AGE 68, 5000 | |
| | TIME - U | NK/NR | C-GWUY | PX- | 5 | 0 | 0 | PLEASURE/PERSONAL TRANSP | TOTAL HOURS, 6 IN TYPE, | |
| | | | DAMAGE-DESTROYED | OT- | 0 | 0 | 0 0 NOT INSTRUMENT RA | | | |
| | | | INTENDED DESTINATION | | | | | | | |
| | | | WRANGELL,AK | | _ | | | | | |
| | TYPE OF ACCIDENT | | | | PHASE OF OPERATION | | | | | |
| | ,,, | | | | | IN FLIGHT: NORMAL CRUISE | | | | |
| | | PROBABLE CAUSE(S) | | | | | | | | |
| | PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING | | | | | | | | | |
| | PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS | | | | | | | | | |
| | FACTOR(S) WEATHER - LOW CEILING | | | | | | | | | |
| | WEATHER - FOG | | | | | | | | | |
| | WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, IN PERSON | | | | | | | | | |
| | WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT | | | | | | | | | |
| | SKY CONDITION | | | | (| CEILING AT ACCIDENT SITE | | | | |
| | OVERCAST | | | | | 900 | | | | |
| | VISIBILITY AT ACCIDENT SITE | | | | | PRECIPITATION AT ACCIDENT SITE | | | | |
| | 4 MILES OR LESS | | | | | RAIN SHOWERS | | | | |
| | OBSTRUCT: | IONS TO VISION AT AC | ACCIDENT SITE | | | | TEMPERATURE-F | | | |
| | FOG | | | | | 61 | | | | |
| | TYPE OF WEATHER CONDITIONS | | | | Т | TYPE OF FLIGHT PLAN | | | | |
| | IFR | | | | | VFR | | | | |
| | FIRE AFTER IMPACT | | | | | | | | | |
| | REMARKS- | HIT MTN 3000FT MSL. | | | | | | | | |

Full narrative is not available