

NTSB Identification: DEN77FTC19

14 CFR Part 91 General Aviation
 Aircraft: DOUGLAS DC-3A, registration: N459

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2067	77/7/18	NR.SHERIDAN,WY	DOUGLAS DC-3A	CR- 2 0 0	COMMERCIAL	COMMERCIAL, AGE 56, 8530
	TIME - 0535		N459	PX- 0 0 0	AERIAL APPLICATION	TOTAL HOURS, 3000 IN
			DAMAGE-DESTROYED	OT- 0 0 0		TYPE, INSTRUMENT RATED.
	DEPARTURE POINT		INTENDED DESTINATION			
	SHERIDAN,WY		RETURN			
	TYPE OF ACCIDENT				PHASE OF OPERATION	
	STALL: SPIRAL				IN FLIGHT: PROCEDURE TURNAROUND	
	PROBABLE CAUSE(S)					
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING					
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING					
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED					
	MISCELLANEOUS ACTS,CONDITIONS - FLEW INTO BLIND CANYON					
	SPECIAL DATA					
	TOTAL HOURS IN CROP CONTROL - UNKNOWN/NOT REPORTED				KIND OF OPERATION - SPRAYING CROPS	
	KIND OF CROP - OTHER				TYPE OF CHEMICAL USED - LIQUID CHEMICAL-TOXIC	
	PILOT' S SEAT BELT -UNKNOWN/NOT REPORTED				GLOVES - NOT USED	
	GOGGLES - NOT USED				CRASH HELMET - NOT AVAILABLE	
	COCKPIT CRASHPAD - NOT INSTALLED				CRASH BAR - NOT INSTALLED	
	TANK/HOPPER-LOCATION - AFT OF PILOT				TERRAIN-TYPE -ROLLING	
	ELEVATION-AREA BEING TREATED-FEET - 4200				HILLY	
	SWATH RUN-HOW FLOWN - WIND CALM				PROCEDURE TURNAROUND - SECOND 1/3 TURN	
	FIRE AFTER IMPACT					
	REMARKS- SPRAYING PASTURE LAND FOR GRASSHOPPERS					

Full narrative is not available