

NTSB Identification: ANC78FA043

14 CFR Part 135 Nonscheduled operation of SOUTHEAST SKYW
 Aircraft: DEHAVILLAND DHC-2, registration: N8690

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3530	78/7/3 TIME - 1930	NR.PELICAN,AK	DEHAVILLAND DHC-2 N8690 DAMAGE-DESTROYED	CR- PX- OT-	0 0 0	1 1 0	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, FL.INSTR., AGE 29, 5150 TOTAL HOURS, 125 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION		PHASE OF OPERATION				
ELFIN COVE,AK		HERBERT GRAVES IS,AK		IN FLIGHT: NORMAL CRUISE				
TYPE OF ACCIDENT								
STALL: SPIRAL								
PROBABLE CAUSE(S)								
PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING								
PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS								
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED								
FACTOR(S)								
WEATHER - LOW CEILING								
WEATHER - FOG								
TERRAIN - HIGH OBSTRUCTIONS								
MISCELLANEOUS ACTS,CONDITIONS - FLEW INTO BLIND CANYON								
WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED								
WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT								
SKY CONDITION				CEILING AT ACCIDENT SITE				
OVERCAST				UNKNOWN/NOT REPORTED				
VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE				
3 MILES OR LESS				NONE				
OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F				
FOG				50				
TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN				
IFR				VFR				
REMARKS- FLOAT EQUIPPED. ENTERED NARROW CHANNEL AT 100FT AGL.								

Full narrative is not available