## NTSB Identification: ANC80DAH02

14 CFR Part 135 Nonscheduled operation of BUSH AIR,INC. Aircraft: CESSNA 207, registration: N1712U

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N					PILOT DATA	
3-3625	80/8/27 NI	P DATMIIT AK	CESSNA 207						COMMERCIAL, AGE 35, 1655	
5 5025	TIME - 1920							AIR TAXI-CARGO		
			DAMAGE-DESTROYED						INSTRUMENT RATED.	
	DEPARTURE POINT									
	BETHEL,AK		HOLY CROSS,AK					N/NOT REPORTED		
	TYPE OF ACCIDENT				Р			OPERATION		
		FAILURE OR MALFU	NCTION		IN FLIGHT: NORMAL CRUISE					
	NOSE OVER/DOWN				LANDING: ROLL					
	PROBABLE CAUSE(S)									
	PERSONNEL - MAINTENANCE, SERVICING, INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION									
	POWERPLANT - ENGINE STRUCTURE: OTHER									
	MISCELLANEOUS ACTS, CONDITIONS - LACK OF LUBRICATION-SPECIFIC PART, NOT SYSTEM									
	MISCELLANEOUS ACTS, CONDITIONS - MATERIAL FAILURE									
	FACTOR(S)									
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING									
	POWERPLANT - PROPELLER AND ACCESSORIES: GOVERNORS									
	MISCELLANEOUS ACTS, CONDITIONS - RPM-UNCONTROLLABLE-OVERSPEED									
	TERRAIN - ROUGH/UNEVEN									
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND									
	REMARKS- NR 4 MAIN BRG TURNED, LUBE PASSAGES NOT ALIGNED. CRANKCASE HALVES LOOSE. OIL VERY BLACK, TARRY.									
	KLEAKKS N	IN 4 INATIN DIG TON	NLD, LODE FASSAGES NOT A	LIGINEI	). CN	MINI	CAS	I HALVES LOOSE. OIL VERY	DLACK, TAKKT.	

Full narrative is not available