

NTSB Identification: ANC81FA028

14 CFR Part 91 General Aviation
Aircraft: DEHAVND CAN DHC-2, registration: N6473

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-0817	81/3/14	NR.KENAI,AK	DEHAVND CAN DHC-2	CR-	1	0	0	NONCOMMERCIAL	COMMERCIAL, AGE 34, 2304 TOTAL HOURS, 702 IN TYPE, INSTRUMENT RATED.
	TIME - 1500		N6473	PX-	0	1	0	BUSINESS	
			DAMAGE-SUBSTANTIAL	OT-	0	0	0		
	DEPARTURE POINT		INTENDED DESTINATION						
	ANCHORAGE,AK		EAST TWIN LAKE,AK						
	TYPE OF ACCIDENT							PHASE OF OPERATION	
	STALL: MUSH							IN FLIGHT: OTHER	
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED								
	PILOT IN COMMAND - EXERCISED POOR JUDGMENT								
	FACTOR(S)								
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
	MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.								
	WEATHER - UNFAVORABLE WIND CONDITIONS								
	WEATHER BRIEFING - UNKNOWN/NOT REPORTED								
	WEATHER FORECAST - UNKNOWN/NOT REPORTED								
	SKY CONDITION							CEILING AT ACCIDENT SITE	
	OVERCAST							2000	
	VISIBILITY AT ACCIDENT SITE							PRECIPITATION AT ACCIDENT SITE	
	4 MILES OR LESS							SNOW SHOWERS	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE							TYPE OF WEATHER CONDITIONS	
	BLOWING SNOW							VFR	
	TYPE OF FLIGHT PLAN								
	NONE								
	REMARKS- LOW LEVEL TURN.ACFT AT LEAST 1,230LBS OVR G/W & 5% OF MAC AFT OF REAR CG LIMITS.								

Full narrative is not available