## NTSB Identification: ATL81FKG10

14 CFR Part 91 General Aviation Aircraft: BEECH D18, registration: N80162

FILE	DATE LOCATION		AIRCRAFT DATA			FLIGHT PURPOSE	PILOT DATA
3-0265	TIME - 21	IRPORT - CLAYTON	BEECH D18 N80162 DAMAGE-SUBSTANTIAL	PX- 0 1	0	NONCOMMERCIAL BUSINESS	COMMERCIAL, AGE 57, 6024 TOTAL HOURS, 638 IN TYPE INSTRUMENT RATED.
	FT LAUDERDALE,FL						
	TYPE OF ACCIDENT			PHASE OF OPERATION			
	ENGINE FAILURE OR MALFUNCTION			LANDING: FINAL APPROACH			
	COLLID	ED WITH: TREES		LANDING: FINAL APPROACH			
	PROBABLE CAUSE(S)						
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
	PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
	MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION						
	FACTOR(S)						
	MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES						
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES						
		CTD CUMCTANGES	FORCED LANDING OFF AIRPO				

Full narrative is not available