

NTSB Identification: ANC81FA093

14 CFR Part 135 Nonscheduled operation of SOUTHEAST ALAS
 Aircraft: DEHAVILLAND DHC-2, registration: N31618

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3640	81/8/7 TIME - 1030	NR.KETCHIKAN,AK	DEHAVILLAND DHC-2 N31618 DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 4 1 OT- 0 0 0	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, AGE 26, 1671 TOTAL HOURS, 541 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT KETCHIKAN,AK	INTENDED DESTINATION RETURN			LAST ENROUTE STOP UNKNOWN/NOT REPORTED	
	TYPE OF ACCIDENT COLLISION WITH GROUND/WATER: UNCONTROLLED				PHASE OF OPERATION IN FLIGHT: UNCONTROLLED DESCENT	
	PROBABLE CAUSE(S) PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS PILOT IN COMMAND - BECAME LOST/DISORIENTED PILOT IN COMMAND - SPATIAL DISORIENTATION					
	FACTOR(S) WEATHER - FOG WEATHER BRIEFING - BRIEFING RECEIVED-METHOD UNKNOWN WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT					
	SKY CONDITION OBSCURATION				CEILING AT ACCIDENT SITE UNKNOWN/NOT REPORTED	
	VISIBILITY AT ACCIDENT SITE ZERO				PRECIPITATION AT ACCIDENT SITE NONE	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE FOG				TEMPERATURE-F 63	
	WIND VELOCITY-KNOTS CALM				TYPE OF WEATHER CONDITIONS IFR	
	TYPE OF FLIGHT PLAN OTHER					
	FIRE AFTER IMPACT REMARKS- FLOAT EQUIPPED.CO FLT PLN.					

Full narrative is not available