NTSB Identification: DEN81FA050

14 CFR Part 91 General Aviation Aircraft: PIPER 602P, registration: N68904

FILE	DATE LOCA	ATION AIRCRAFT DATA	F	SI	1/N	FLIGHT PURPOSE	PILOT DATA	
3-2448	81/7/17 NR.MEAD,CC TIME - 1710	PIPER 602P N68904 DAMAGE-DESTROYED	CR- 1 PX- 1	. 0	0 0	NONCOMMERCIAL	PRIVATE, AGE 44, 668	
	DEPARTURE POINT GRAND JUNCTION,CO	INTENDED DESTINATION WALDEN,CO						
	TYPE OF ACCIDENT				PHASE OF OPERATION			
	STALL: SPIN IN FLI				LIGHT: NORMAL CRUISE			
	PROBABLE CAUSE(S)							
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING							
	PILOT IN COMMAND - BECAME LOST/DISORIENTED							
	PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS							
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED							
	FACTOR(S)							
	WEATHER - RAIN							
	WEATHER - LOW CE WEATHER - THUNDE							
	WEATHER BRITEFING - NO RECORD OF BRITEFING RECEIVED							
	MEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT							
	SKY CONDITION			CEII	ING	AT ACCIDENT SITE		
	OBSCURATION			-	00			
	VISIBILITY AT ACCID	DENT SITE		PRE	IPI	TATION AT ACCIDENT SITE		
	1/2 MILE OR LESS			-	RAIN	SHOWERS, THUNDERSTORM		
	OBSTRUCTIONS TO VIS	SION AT ACCIDENT SITE		TYPI	OF	WEATHER CONDITIONS		
	NONE			I	R			
	TYPE OF FLIGHT PLAN	I						
	NONE							

Full narrative is not available