

NTSB Identification: MKC81FA050

14 CFR Part 91 General Aviation
Aircraft: BEECH 65, registration: N805Q

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-2198	81/8/7	SPIRIT LAKE, IA	BEECH 65 N805Q DAMAGE-DESTROYED	CR- 0	1 0	NONCOMMERCIAL	COMMERCIAL, FL.INSTR., AGE 63, 21500 TOTAL HOURS, 7820 IN TYPE, INSTRUMENT RATED.	
	TIME - 1720			PX- 0	4 1	CORP/EXEC		
				OT- 0	0 0			
NAME OF AIRPORT - SPIRIT LAKE MUNI								
DEPARTURE POINT		INTENDED DESTINATION						
ROCKFORD, IL		SPIRIT LAKE, IA						
TYPE OF ACCIDENT				PHASE OF OPERATION				
ENGINE FAILURE OR MALFUNCTION				LANDING: FINAL APPROACH				
STALL				LANDING: FINAL APPROACH				
PROBABLE CAUSE(S)								
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS								
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.								
MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES								
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED								
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE								
FIRE AFTER IMPACT								
REMARKS- PLT STATED L ENG MALFUNCTIONED ON FINAL. L PROP SLASH MARKS FD 21IN APART, PROP NOT FEATHERED.								

Full narrative is not available