

NTSB Identification: OAK71FVA08

14 CFR Part 91 General Aviation
 Aircraft: CONVAIR PBY-6A, registration: N6459C

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-1502	70/7/18 TIME - 1600	COLUMBIA,CALIF	CONVAIR PBY-6A N6459C DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL ASSOC FIRE CTL ACTIVITY	COMMERCIAL, AGE 58, 13532 TOTAL HOURS, 1202 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - COLUMBIA DEPARTURE POINT INTENDED DESTINATION COLUMBIA,CALIF LOCAL TYPE OF ACCIDENT PHASE OF OPERATION UNDERSHOOT LANDING: FINAL APPROACH COLLIDED WITH: OBJECT LANDING: LEVEL OFF/TOUCHDOWN PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED DISTANCE,SPEED,AND ALTITUDE TERRAIN - OTHER FACTOR(S) MISCELLANEOUS ACTS,CONDITIONS - DOWNWIND WEATHER - HIGH TEMPERATURE WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED WEATHER FORECAST - UNKNOWN/NOT REPORTED SKY CONDITION CEILING AT ACCIDENT SITE CLEAR UNLIMITED VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE 5 OR OVER(UNLIMITED) NONE OBSTRUCTIONS TO VISION AT ACCIDENT SITE RELATIVE BEARING OF WIND NONE LEFT QUARTERING TAIL WIND 203-247 DEGREES TEMPERATURE-F WIND DIRECTION-DEGREES 101 193 WIND VELOCITY-KNOTS TYPE OF WEATHER CONDITIONS 8 VFR TYPE OF FLIGHT PLAN NONE FIRE AFTER IMPACT REMARKS- ACFT OBSD MAKING 360 TURNS LO ALT.PLT REPD FNL APCH.HIT GRANITE BOULDERS 252 FT SHORT,5 FT BLO RWY						

Full narrative is not available