

NTSB Identification: ANC74AA063

14 CFR Part 135 Scheduled operation of MUNZ NORTHERN*
 Aircraft: DORNIER DO-28D, registration: N3799

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-0807	74/4/3 TIME - 0900	ELIM,ALAS	DORNIER DO-28D N3799 DAMAGE-SUBSTANTIAL	CR- PX- OT-	0 0 0	1 1 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	COMMERCIAL, FL.INSTR., AGE 30, 4745 TOTAL HOURS, 53 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - ELIM VILLAGE DEPARTURE POINT INTENDED DESTINATION NOME,ALAS ELIM,ALAS TYPE OF ACCIDENT PHASE OF OPERATION COLLIDED WITH: SNOWBANK LANDING: ROLL PROBABLE CAUSE(S) PILOT IN COMMAND - SELECTED UNSUITABLE TERRAIN PILOT IN COMMAND - FAILED TO INITIATE GO-AROUND FACTOR(S) AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: ICE/SLUSH ON RUNWAY REMARKS- OVERRAN RWY,HIT SNOW BERM & SNOW MACHINE.								

Full narrative is not available