

NTSB Identification: ANC75AA010

14 CFR Part 135 Nonscheduled operation of MERRIC AVN.
 Aircraft: DEHAVILLAND DHC-2, registration: N7620

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3159	74/8/13 TIME - 1835	NR. ANAKTUVUK, ALAS	DEHAVILLAND DHC-2 N7620 DAMAGE-DESTROYED	CR- PX- OT-	1 3 0	0 0 0	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, FL.INSTR., AGE 28, 1862 TOTAL HOURS, 235 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - CHANDALAR CAMP DEPARTURE POINT INTENDED DESTINATION LAST ENROUTE STOP DIETRICH, ALAS HAPPY VALLEY, ALAS CHANDALAR, ALAS TYPE OF ACCIDENT PHASE OF OPERATION COLLISION WITH GROUND/WATER: CONTROLLED IN FLIGHT: NORMAL CRUISE PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING FACTOR(S) PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS TERRAIN - HIGH OBSTRUCTIONS WEATHER - LOW CEILING WEATHER - FOG WEATHER BRIEFING - COMPANY DISPATCH WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT SKY CONDITION CEILING AT ACCIDENT SITE OVERCAST 500 VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE 3 MILES OR LESS NONE OBSTRUCTIONS TO VISION AT ACCIDENT SITE TYPE OF WEATHER CONDITIONS FOG VFR TYPE OF FLIGHT PLAN VFR REMARKS- TRIED TO FLY THRU OBSCURED MTN PASS.UN CONT,TURNED AROUND & HIT GND.								

Full narrative is not available