NTSB Identification: CHI75AC046

14 CFR Part 91 General Aviation Aircraft: NA ROCKWELL 265-60, registration: N920G

FILE	DATE	LOCATION	AIRCRAFT DATA			IES S M		FLIGHT PURPOSE	PILOT DATA
3-4318	74/12/27 NR. TIME - 2005	LANCASTER,OHIO	NA ROCKWELL 265-60 N920G DAMAGE-DESTROYED	PX-	0	0	0	NONCOMMERCIAL CORP/EXEC	ATP,FLIGHT INSTR., AGE 45, 15105 TOTAL HOURS, 367 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - FAIRFIELD COUNTY
DEPARTURE POINT INTENDED DESTINATION
DENVER,COLO LANCASTER,OHIO
TYPE OF ACCIDENT

PHASE OF OPERATION COLLIDED WITH: TREES LANDING: OTHER

PROBABLE CAUSE(S)
PILOT IN COMMAND - IMPROPER IFR OPERATION
MISCELLANEOUS ACTS, CONDITIONS - DISREGARD OF GOOD OPERATING PRACTICE MISCELLANEOUS ACTS, CONDITIONS - DISREGARD OF GOOD OPERATING PRACTICE FACTOR(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING TERRAIN - HIGH OBSTRUCTIONS FIRE AFTER IMPACT

REMARKS- NON-STANDARD APCH IN NIGHT-INSTRUMENT CONDITIONS.FLEW INTO MOUNTAIN.

Full narrative is not available