

# NTSB Identification: ANC76AA082

14 CFR Part 135 Scheduled operation of FRONTIER FLYIN  
 Aircraft: CESSNA 207, registration: N1707U

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2850	76/4/27 TIME - 1115	NR.ANAKTUVUK PASS,AK	CESSNA 207 N1707U DAMAGE-DESTROYED	CR- 1 0 0 PX- 4 0 0 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	COMMERCIAL, AGE 52, 1744 TOTAL HOURS, 35 IN TYPE, INSTRUMENT RATED.
		DEPARTURE POINT ANAKTUVUK PASS,AK	INTENDED DESTINATION BETTLES,AK	PHASE OF OPERATION IN FLIGHT: NORMAL CRUISE		
TYPE OF ACCIDENT COLLISION WITH GROUND/WATER: CONTROLLED						
PROBABLE CAUSE(S) PILOT IN COMMAND - INITIATED FLIGHT IN ADVERSE WEATHER CONDITIONS						
FACTOR(S) WEATHER - LOW CEILING WEATHER - SNOW MISCELLANEOUS ACTS,CONDITIONS - WHITEOUT						
WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE						
WEATHER FORECAST - WEATHER SLIGHTLY WORSE THAN FORECAST						
SKY CONDITION OVERCAST				CEILING AT ACCIDENT SITE UNKNOWN/NOT REPORTED		
VISIBILITY AT ACCIDENT SITE 1/2 MILE OR LESS				PRECIPITATION AT ACCIDENT SITE SNOW SHOWERS		
OBSTRUCTIONS TO VISION AT ACCIDENT SITE BLOWING SNOW				TYPE OF WEATHER CONDITIONS BELOW MINIMUMS		
TYPE OF FLIGHT PLAN VFR						
REMARKS- PLT HAD JUST FLOWN THRU SAME WEA.OPERATING UNDER SUBCONTRACT AS WIEN AIR ALASKA FLT 528.						

Full narrative is not available