

NTSB Identification: ANC76AA096

14 CFR Part 135 Scheduled operation of ALASKA AERONA*
 Aircraft: CESSNA 402, registration: N4049Q

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2754	76/6/11 TIME - 0750	NR.SUMMIT LAKE,AK	CESSNA 402 N4049Q DAMAGE-DESTROYED	CR- 1 0 0 PX- 1 0 0 OT- 2 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	ATP, FLIGHT INSTR., AGE 32, 4000 TOTAL HOURS, 72 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
ANCHORAGE AK		SEWARD AK				
TYPE OF ACCIDENT				PHASE OF OPERATION		
COLLISION WITH AIRCRAFT: BOTH IN FLIGHT				IN FLIGHT: NORMAL CRUISE		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - FAILED TO SEE AND AVOID OTHER AIRCRAFT						
PERSONNEL - MISCELLANEOUS-PERSONNEL: PILOT OF OTHER AIRCRAFT						
SPECIAL DATA						
SEGMENTS OF AVIATION INVOLVED - SMALL US GEN.AV.-SMALL US GEN.AV.						
CONTROLLING AGENCY - NO CONTROL				RADAR CTL/SURVEILLANCE - NOT UNDER RADAR CONTACT		
TRAFFIC ADVISORY ISSUED - NONE				CONTROL ZONE/AREA - NO		
CONVERGENCE ANGLE-DEGREES - 150				EVASIVE ACTION TAKEN - UNKNOWN/NOT REPORTED		
ANTI-COLLISION LIGHTS - OPERATING						
REMARKS- FLT 501 WAS OBSERVED PARALLELING SEWARD-ANCHORAGE HIGHWAY AT APPROX 1000 FT.						

Full narrative is not available