

# NTSB Identification: OAK77FA020

14 CFR Part 91 General Aviation  
Aircraft: LOCKHEED 18-56, registration: N100GP

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0679	77/2/21 TIME - 1620	TRUCKEE, CA	LOCKHEED 18-56 N100GP DAMAGE-DESTROYED	CR- 0 0 2 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL BUSINESS	ATP, FLIGHT INSTR., AGE 31, 7191 TOTAL HOURS, 15 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - TRUCKEE-TAHOE						
DEPARTURE POINT		INTENDED DESTINATION				
TRUCKEE, CA		UNKNOWN/NOT REPORTED				
TYPE OF ACCIDENT				PHASE OF OPERATION		
STALL: MUSH				TAKEOFF: INITIAL CLIMB		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
MISCELLANEOUS ACTS, CONDITIONS - AIRFRAME ICE						
FIRE AFTER IMPACT						
REMARKS- 12IN SPANWISE ICE STRIP ON UPPER WING SURFACE.						

Full narrative is not available