NTSB Identification: CHI77FA006

14 CFR Part 91 General Aviation Aircraft: PIPER PA-31, registration: N74941

FILE	DATE L	OCATION	AIRCRAFT DATA				FLIGHT PURPOSE	PILOT DATA
3-4147	76/11/11 SPRIN TIME - 1636	G LAKE,MI	PIPER PA-31 N74941 DAMAGE-DESTROYED	PX-	1 5	2		PRIVATE, AGE 51, 1798 TOTAL HOURS, 221 IN TYPE INSTRUMENT RATED.
	NAME OF AIRPORT - MUSKEGON COUNTY DEPARTURE POINT INTENDED DESTINATION							
	TRAVERSE CITY,MI GRAND HAVEN,MI TYPE OF ACCIDENT			PHASE OF OPERATION				
	ENGINE FAILURE OR MALFUNCTION			IN FLIGHT: NORMAL CRUISE				
	STALL			LANDING: FINAL APPROACH				
	PROBABLE CAUSE(S)							
	PILOT IN COMMAND - MISMANAGEMENT OF FUEL							
	MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION							
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED							
	PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.							
	MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES FACTOR(S)							
	PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT POWERPLANT - FUEL SYSTEM: PUMPS							
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES							
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND							
	REMARKS- R BOOST PUMP INOP,X-FEED USED TO START R ENG.X-FEED FOUND ON,L INBOARD TANK DRY							K DRY.

Full narrative is not available