

NTSB Identification: SEA78FA001

14 CFR Part 135 Nonscheduled operation of KENMORE AIR HA
Aircraft: DEHAVILLAND DHC-2, registration: N64391

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3392	77/10/1	STEVENS PASS,WA	DEHAVILLAND DHC-2	CR-	1	0	0	COMMERCIAL
	TIME - 1400		N64391	PX-	6	0	0	AIR TAXI-PASSG
			DAMAGE-DESTROYED	OT-	0	0	0	ATP,FLIGHT INSTR., AGE
								25, 4122 TOTAL HOURS, 799
								IN TYPE, INSTRUMENT
								RATED.
		DEPARTURE POINT	INTENDED DESTINATION	LAST ENROUTE STOP				
		KENMORE,WA	LK HATHEUME,CANADA	PENTICTON,BC,CANADA				
		TYPE OF ACCIDENT		PHASE OF OPERATION				
		COLLIDED WITH: TREES		IN FLIGHT: CLIMB TO CRUISE				
		PROBABLE CAUSE(S)						
		PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING						
		MISCELLANEOUS ACTS,CONDITIONS - UNWARRANTED LOW FLYING						
		PILOT IN COMMAND - MISJUDGED DISTANCE,SPEED,AND ALTITUDE						
		FACTOR(S)						
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
		MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.						
		TERRAIN - HIGH OBSTRUCTIONS						
		FIRE AFTER IMPACT						
		REMARKS- LOW FLT THRU CANYON APPROACHING MTN PASS.UNABLE TO OUTCLIMB RISING TERRAIN.EXCEEDED GWT & AFT CG.						

Full narrative is not available