NTSB Identification: MIA78FA090

14 CFR Part 91 General Aviation Aircraft: CONVAIR 880, registration: N8815E

FILE	DATE	LOCATION	AIRCRAFT DATA		NJURIES F S M/N			FLIGHT PURPOSE	PILOT DATA
3-2897	78/5/25 TIME - 075	MIAMI,FL 55	CONVAIR 880 N8815E DAMAGE-SUBSTANTIAL	PX-	0	0	3	NONCOMMERCIAL CORP/EXEC	AIRLINE TRANSPORT, AGE 56, 40000 TOTAL HOURS, 8000 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - MIAMI INTL
DEPARTURE POINT INTENDED DESTINATION
MIAMI,FL ST.MAARTEN,NETS
TYPE OF ACCIDENT
GEAR COLLAPSED PHASE OF OPERATION TAKEOFF: ABORTED

PROBABLE CAUSE(S)
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING
MISCELLANEOUS ACTS, CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.

FACTOR(S)

PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL: DEFICIENCY, COMPANY MAINTAINED EQPMT, SERVICES, REGULATION MISCELLANEOUS ACTS, CONDITIONS - RAN OFF END OF RUNWAY MISCELLANEOUS ACTS, CONDITIONS - OVERLOAD FAILURE REMARKS- A/C TRAVELLED 285FT INTO OVERRUN FOL ABORT TKOF. FORWARD C/G EXCEEDED LIMIT BY 12.61 PER CENT MAC.

Full narrative is not available