

NTSB Identification: MIA79DA104

14 CFR Part 135 Nonscheduled operation of PALM BEACH AVI
Aircraft: AERO COMDR 500, registration: N3836C

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES				FLIGHT PURPOSE	PILOT DATA
				F	S	M	N		
3-2839	79/5/17	NR.TREASURE CAY,BAHM	AERO COMDR 500	CR-	0	0	1	COMMERCIAL	COMMERCIAL, AGE 34, 3770
	TIME - 1715		N3836C	PX-	0	0	0	AIR TAXI-PASSG	TOTAL HOURS, 1077 IN
			DAMAGE-DESTROYED	OT-	0	0	0		TYPE, INSTRUMENT RATED.
		DEPARTURE POINT	INTENDED DESTINATION						
		TREASURE CAY,BAHAMAS	ANDROS TOWN,BAHAMAS						
		TYPE OF ACCIDENT		PHASE OF OPERATION					
		ENGINE FAILURE OR MALFUNCTION		TAKEOFF: INITIAL CLIMB					
		DITCHING		LANDING: LEVEL OFF/TOUCHDOWN					
		PROBABLE CAUSE(S)							
		POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS							
		PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.							
		MISCELLANEOUS ACTS,CONDITIONS - IMPROPER EMERGENCY PROCEDURES							
		FACTOR(S)							
		MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER							
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE							
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER							
		REMARKS- HIT TREES NEAR RWY AFTR ENG FAILURE.UN MAINTAIN ALTITUDE,DITCHED IN INTL WATERS.							

Full narrative is not available