

NTSB Identification: MIA79AA049

14 CFR Part 91 General Aviation
Aircraft: DOUGLAS DC-9, registration: N8910E

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA		
				F	S	M/N				
1-0016	79/2/9	NR.MIAMI,FL	DOUGLAS DC-9	CR-	0	2	2	TRAINING	AIRLINE TRANSPORT, AGE 45, 12898 TOTAL HOURS, 1959 IN TYPE, INSTRUMENT RATED.	
	TIME - 1712		N8910E	PX-	0	0	1			
			DAMAGE-DESTROYED	OT-	0	0	0			
	NAME OF AIRPORT - DADE-COLLIER JET									
	OPERATOR - EASTERN AIR LINES,INC.									
	DEPARTURE POINT		INTENDED DESTINATION							
	MIAMI,FL		LOCAL							
	TYPE OF ACCIDENT				PHASE OF OPERATION					
	COLLISION WITH GROUND/WATER: UNCONTROLLED				TAKEOFF: INITIAL CLIMB					
	PROBABLE CAUSE(S)									
	COPILOT - IMPROPER OPERATION OF FLIGHT CONTROLS									
	COPILOT - LACK OF FAMILIARITY WITH AIRCRAFT									
	PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT									
	FACTOR(S)									
	MISCELLANEOUS ACTS,CONDITIONS - SIMULATED CONDITIONS									
	REMARKS- FIRST OFFICER TRAINEE UPGRADE TRNG FLT.CHECK CAPTAIN ADM SIMULATED LEFT ENGINE FAILURE AT LIFTOFF.									

Full narrative is not available