

NTSB Identification: NYC79FA103

14 CFR Part 135 Scheduled operation of MOUNTAIN AIR C
 Aircraft: BEECH E18S, registration: N705M

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3902	79/9/19 TIME - 0404	SUFFIELD,CT	BEECH E18S N705M DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	COMMERCIAL, AGE 37, 6425 TOTAL HOURS, 125 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - BRADLEY INTL						
DEPARTURE POINT		INTENDED DESTINATION				
SUFFIELD,CT		BALTIMORE,MD				
TYPE OF ACCIDENT				PHASE OF OPERATION		
COLLISION WITH GROUND/WATER: UNCONTROLLED				TAKEOFF: INITIAL CLIMB		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
MISCELLANEOUS ACTS,CONDITIONS - CARGO SHIFTED						
MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.						
FIRE AFTER IMPACT						
REMARKS- TIE-DOWN SNAPS,RINGS FOUND DISCONNECTED.682LBS OVER MAX GWT.						

Full narrative is not available