## NTSB Identification: NYC81FA050

14 CFR Part 135 Nonscheduled operation of GULL AIR INC Aircraft: BEECH G18S, registration: N75LA

FILE	DATE	LOCATION	AIRCRAFT DATA	 	IES S M		FLIGHT PURPOSE	PILOT DATA
3-2878	81/5/23 TIME - 055	HYANNIS,MA 55	BEECH G18S N75LA DAMAGE-DESTROYED	 0	0	0	COMMERCIAL AIR TAXI-CARGO	AIRLINE TRANSPORT, AGE 27, 3500 TOTAL HOURS, 171 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - BARNSTABLE MUNI
DEPARTURE POINT INTENDED DESTINATION
HYANNIS,MA NANTUCKET,MA

TYPE OF ACCIDENT PHASE OF OPERATION COLLISION WITH GROUND/WATER: UNCONTROLLED TAKEOFF: INITIAL CLIMB

PROBABLE CAUSE(S)

PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING
MISCELLANEOUS ACTS, CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.
REMARKS- APRX 1551 LBS OVR MAX GROSS WT & 31.25 IN BHND AFT CG LMT.MODIFIED BY HAMILTON IAW STC 1995W.

Full narrative is not available