

# NTSB Identification: FTW81FA124

14 CFR Part 91 General Aviation  
 Aircraft: CESSNA 401, registration: N441RS

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-2540	81/7/22 TIME - 1230	ALBUQUERQUE, NM	CESSNA 401 N441RS DAMAGE-DESTROYED	CR- 1	0	0	MISCELLANEOUS FERRY	ATP, FLIGHT INSTR., AGE 33, 6650 TOTAL HOURS, 1020 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - ALAMEDA DEPARTURE POINT ALBUQUERQUE, NM TYPE OF ACCIDENT STALL: MUSH PROBABLE CAUSE(S) PILOT IN COMMAND - MISUNDERSTANDING OF ORDERS OR INSTRUCTIONS PILOT IN COMMAND - SELECTED WRONG RUNWAY RELATIVE TO EXISTING WIND PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING FACTOR(S) AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: OTHER WEATHER - HIGH DENSITY ALTITUDE SKY CONDITION SCATTERED VISIBILITY AT ACCIDENT SITE 5 OR OVER(UNLIMITED) OBSTRUCTIONS TO VISION AT ACCIDENT SITE NONE WIND DIRECTION-DEGREES 340 TYPE OF WEATHER CONDITIONS VFR FIRE AFTER IMPACT REMARKS- PLT THOUGHT FERRY PERMIT PROHIBITED USE OF LONGER RWY DUE POPULATED AREA.DA 9000FT.UPHILL GRADIENT								
INTENDED DESTINATION CHESAPEAKE, VA LAST ENROUTE STOP SANTA ROSA, NM PHASE OF OPERATION TAKEOFF: INITIAL CLIMB CEILING AT ACCIDENT SITE UNLIMITED PRECIPITATION AT ACCIDENT SITE NONE TEMPERATURE-F 94 WIND VELOCITY-KNOTS 7 TYPE OF FLIGHT PLAN NONE								

Full narrative is not available